


↕ OF FRAME

○ HOLES PUNCHED IN PURLINS

● BOLTED HOLES



#8 PUNCH  
(4' LAP CONDITION)